
F16, 1



F16.2


20


Compress quantity of MgBz powder Lzz

Sinter the quantity
of Mg Bz powder while
being compressed

Cool the sintered body

26





F16.5

Provide solid pellet of MgBz Direct beam of Fulsed laser onto the pellet to eject particles of MgBz

